





Assumption of the Blessed Virgin REDENHALL Norfolk

The Issue

Redenhall is a large, spectacular hill-top church with flint flushwork on the tall tower. The church has a unique double headed eagle which had to be permanently covered to prevent damage from bat urine and droppings The church had a large spread of Natterer's and Pipistrelle droppings throughout the church,



and the small community were finding cleaning this large church increasingly difficult.

What We Did

Unfortunately since joining the project the church has been considering closure and has been unable to move ahead with any events or activities.

The church have had a new statement of significance, highlighting any potential areas of damage by bats which should help the church decide how it is to be preserved in the future.





batsinchurches.org.uk











